

FIELD INSPECTION REPORT


Date of Inspection: 18/01/2021	District: Kishanganj
Division: Kishanganj-1	Length(km): 0.820
Name of the Road: Bairagpur moelho mohana pmgsy road to -	
Scheme/Programme:	mmgsy(ST) hasi niyaz tola
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed /Under Maintenance
Work is a case of:	<input checked="" type="checkbox"/> New Connectivity/ Up gradation / Maintenance

Sl. No	Parameters to be checked	Remarks
1.	Pavement	<input checked="" type="checkbox"/> S/U
a)	Road Junction Condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, <u>exposed aggregates</u> in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No
g)	Compaction of flank / shop & raincuts if any	<input checked="" type="checkbox"/> Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	<input checked="" type="checkbox"/> S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts	<input checked="" type="checkbox"/> S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	<input checked="" type="checkbox"/> S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	<input type="checkbox"/>
Satisfactory but requires Improvement (SRI)	<input checked="" type="checkbox"/> SRI
Unsatisfactory(U)	<input type="checkbox"/>

NAME: Ranjeet Kumar


 (Signature) 18/01/21
 AE