FIELD INSPECTION REPORT

Date of Inspection :		18.1.21	District: Bosilland Length (km): 1-30012	
		3-egysarai	Length (km): 1.900 /2	
Name of	the Road: Me	and High se	holdo Tinkong chowle	,
Scheme/I	rogramme:	MAINTENANCI	Road to No.:	
Package		Ongoing/Complet		
Status of the Project: O Work is a case of: N		New Connectivity	ngoing/Completed/Under Maintenance ew Connectivity/Up gradation/ Maintenance	
		The second secon	Parameters to be checked	
Sl. No.				
].	Pavement S/I			5/1 5
111	Road Junction condition			Sile
b)	Condition of Surfacing			
()	Riding Quality			S/U 5
41	Road Camber			4
	Whether free from defects such as visible cracks, exposed			Yes/No
0)	aggregates in case of CC Pavement.			Yes/No
1)	Contraction Joints provided or not (CC Pavement)			
R)	Compaction of Ilank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
	Condition of railings/slab/approach for Bridges			S/SRI/II
3.	Road Furniture			
,1)	the state of the s			Yes:N-1
4.	Compliance History			
al	Status of ATR's & any others			
				_
Overa	ll Rating	: Satisfactory	(S)	
			but requires Improvement (SRI)	
		Unsatisfacto	ry (U)	

- 18.1.2) Ar

(Signature)

NAME:

DESIGNATION: