

FIELD INSPECTION REPORT

Date of Inspection:	20.07.2024	District:	Garh
Division:	Sagar	Length (km):	1.64
Name of the Road:	Khataula P.M. G.S. Road to Khataula Hanuman tal		
Scheme/Programme:	MAINTENANCE		
Package No.:	M.M. G.S. 16	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Initially Road pavement damaged due to long duration of storm.

20/7/24
(Signature) J.E.

NAME: Vinod Kumar Singh
DESIGNATION: J.E
Daryapur