

FIELD INSPECTION REPORT

Date of Inspection :	17/01/2021	District:	Garroo, Rajbar
Division :	RWD, Garroo	Length (km):	0.885 Km
Name of the Road:	SH 73 At Rikunpur yaday to la.		
Scheme/Programme:	MAINTENANCE	Work not start	
Package No.:		Road Id No.:	
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance <i>Ongoing</i> <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance <i>New connectivity</i>		
Work is a case of:			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SAT	work
b)	Condition of Surfacing	SAT	
c)	Riding Quality	SAT	
d)	Road Camber	SAT	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	not
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		check
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRT/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRT/U	
c)	Condition of railings/slab/approach for Bridges	S/SRT/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Rmy
17/01/2021
(Signature)

NAME: M.D. RAFIQUE ALAM

DESIGNATION: J.E.