FIELD INSPECTION REPORT

| | Division: Red Company Length (km): 0. 760 K.m. Name of the Road: Billiam part to proceed to Keither I Scheme/Programme: MAINTENANCE Work shed Length Package No.: Road Id No.: Status of the Project: Ongoing/Completed/Under Maintenance Oro 9 George | | |
|---|---|------------|--|
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | | |
| SI. No. | Parameters to be checked | Remarks | |
| 1 | Pavement | | |
| a) | Road Junction condition | SAU | |
| b) | Condition of Surfacing | SAU | |
| c) | Riding Quality | SAU | |
| d) | Road Camber | 210 | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | YesAvo | |
| n | Contraction Joints provided or not (CC Pavement) | Yesho | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| 2 | Cross Drainage | Land Marie | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRIA | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRIA | |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 47 | Compliance History | 司体配置 | |
| a) | Status of ATR's & any others | | |
| O | rating: Kycook rojet started | | |
| Overall F | Satisfactory (S) | - | |
| | Satisfactory but requires Improvement (SRI) | | |

(Signature)

ME: MP. RAFIGUE ALAM

DESIGNATION:

J. E.