

FIELD INSPECTION REPORT

Date of Inspection :	19/01/2021	District:	Surya, Bihar
Division :	RWD, Sonpur	Length (km):	0.845 Km
Name of the Road:	Surya Dargah to Mubay road 2017		
Scheme/Programme:	MAINTENANCE	Work not start	
Package No.:		Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance <i>on going</i> ☒ New Connectivity/Up gradation/ Maintenance <i>New connectivity</i>		
Work is a case of:			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	work
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	start
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Earthwork in progress

Satisfactory (S) —
Satisfactory but requires Improvement (SRI) —
Unsatisfactory (U) —

20/1
19/01/2021
(Signature)

MP. RAFIQUE ALAM

T.E.