

FIELD INSPECTION REPORT

Date of Inspection:	28.12.20	District:	East West Champaran
Division:	Barh	Length (km):	2.455 km
Name of the Road:	Manikpur turha to Barh via Shah Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31709313 005
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SL ✓
b)	Condition of Surfacing	SU ✓
c)	Riding Quality	SL ✓
d)	Road Camber	SL ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Construction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of back slope & rainouts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its apron.	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI ✓
c)	Condition of railings/slab approach for bridges	S/SRI ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

28/12/20
(Signature)

NAME: Manish Kumar

DESIGNATION: J-E-R.W.D. Officer