FIELD INSPECTION REPORT

Date of Inspection: 18.1.21	District: Somastiphy	
Division: Samustipur	Length (km):	
Name of the Road: Cobassitte	Dale to Arrusachit Jati Tali	
Scheme/Programme: MAINTENA		
Package No.: MM GBY (SC)	Rond Id No.:	
Status of the Project: Ongoing/Cor	Ongoing/Completed/Under Maintenance	
Work is a case of: New Connec	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
i.	Payement	
a)	Road Junction condition	- 5/U
b)	Condition of Surfacing	~\$/IJ
c)	Riding Quality	S/U
d)	Road Camber	√ 8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Deninage	
a)	Condition of head walls in Hume pipe culverts including its painting	~8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	~S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRIAU
3.	Road Buffilture E	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
() A	Compliance History 1	p. S. State
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)	0
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Cautom Sus.

(Signature)

NAME: