

FIELD INSPECTION REPORT

Date of Inspection : 18.1.21	District: Samastipur
Division : Samastipur	Length (km):
Name of the Road: R.E.O Road Sherochuk to Mahabhatpur Bypass via Benarshi	
Scheme/Programme: MAINTENANCE	
Package No.: MNGBY (S)	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/N/A
b)	Condition of Surfacing	✓/N/A
c)	Riding Quality	✓/N/A
d)	Road Camber	✓/N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Graded Drains	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Pratim Das
J.E.


18/1/21
(Signature)