

FIELD INSPECTION REPORT

Date of Inspection : 19.01.21	District: East Champaran
Division : Areraj	Length (km): 1.83
Name of the Road: Maldahua Tola to Barham Tola	
Scheme/Programme: MAINTENANCE	
Package No.:	Read Id No: 31708301825
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Remarks
1. Pavement	
a) Road Junction condition	
b) Condition of Surfacing	S/U
c) Riding Quality	S/U
d) Road Camber	S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
	Yes/No
a) Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SR/U
c) Condition of railings/slab/approach for Bridges	N/A S/SR/U
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
a) Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	S
Unsatisfactory (U)	

NAME: Hemant Jha

DESIGNATION: A.E.

Areraj

19/01/21
(Signature)

Scanned with CamScanner