

FIELD INSPECTION REPORT

Date of	Inspection :	20/01/21	District: fatna.	
Division: Danabur. Length (km): 0.35				
Vame of	f the Road: 70		uluteper road near hance	men man
144	Programme:	MAINTENANC		
Package			Road Id No.:	
T. Oleval			oing/Completed/Under Maintenance Connectivity/Up gradation/ Maintenance	
20 Sept. 100	E weekship was	Sale 15 Transact 150		er an acceptant of a
SI, No.	200	Parameter	to be checked	Remarks
1	Pavement.			
a)	Road Junction condition			√8/U
b)	Condition of Surfacing			L8/Ü
c)	Riding Quality			<i>√8/</i> U
d)	Road Camber			LSAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
24-14	Cross Draina			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Rumiture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4. 7.	Gomphance History .			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	V
Unsatisfactory (U)	

Name: Nigmanand Makto
DESIGNATION: J. E.