

FIELD INSPECTION REPORT

Date of Inspection: 05/01/21	District: East Champaran	
Division: Arsony	Length (km): 2.544	
Name of the Road: To go Bhagatko Tola.		
Scheme/Programme: MAINTENANCE		
Package No.: 5R-11R-3+3	Road Id No.: 31208300230	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A
Overall Rating		

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	S
Unsatisfactory (U)	

NAME: Hemant Kumar Jha
 DESIGNATION: Asst. Engineer
 Rtd. Arsony

4/02/21
 (Signature)

Scanned with CamScanner