

11/02/2021

FIELD INSPECTION REPORT

Date of Inspection	20/01/21	Location	East Chinnichan
Division	11/02/21	Length (km)	
Name of the Road	Chinnichan to Hombli	ABank-760	
Scheme/Programme	MAINTENANCE		
Package No.		Road Id No.	31110101235
Status of the Project	Ongoing/Completed/Under Maintenance		
Work is a turn off	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Remarks		
a)	Road Junction condition		SU
b)	Condition of Surfacing		SU
c)	Riding Quality		SU
d)	Road Camber		SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Construction Joints provided or not (CC Pavement)		Yes/No
g)	Construction of flush/slope & rainwater if any		Yes/No
a)	Condition of head walls in stone pipe culverts including its painting		SU/SU
b)	Condition of Abutment & Wing walls, slab in RCC culverts		SU/SU
c)	Condition of railings/slab/approach for Bridges	N/A	SU/SU
a)	Whether sign boards/informatory/cautionary Board/lan & 200m marker/Pavement road markings are provided and maintained		Yes/No
a)	Status of ATR's & any others		

WORK NOT STARTED

N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SI)	
Unsatisfactory (U)	

N/A

NAME: HANMANTH JOL
 DESIGNATION: AE
 RWD AITM

11/02/2021
 (Signature)