

MMIGSY: NDB.

FIELD INSPECTION REPORT

Date of Inspection: 21/01/21		District: East clombaron
Division: Arroyal		Length (km):
Name of the Road: Kombaron Horlan Tala To Keri Tala Deru Tala		
Scheme/Programme: MAINTENANCE		Road ID No.:
Project No.:		Project Name:
Status of the Project: Ongoing/Completed/Under Maintenance		Remarks:
Work is a turn off: New Connectivity/Up gradation/ Maintenance		
a) Road Junction condition		S/U
b) Condition of Surfacing		S/U
c) Riding Quality		S/U
d) Road Camber		S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f) Construction Joints provided or not (CC Pavement)		Yes/No
g) Compaction of flank/slope & subgrade if any		Yes/No
a) Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c) Condition of railings/slab/approach for Bridges		S/SR/U
a) Whether sign boards/informative/Warning Board/km & 200m stones/Pavement and markings are provided and maintained		Yes/No
a) State of ATR's & any others		ND

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

4601
21/01/21
(Signature)

NAME: Haradhan Sircar

DESIGNATION: A.E.
RWD Arroyal

Scanned with CamScanner