

FIELD INSPECTION REPORT

Date of Inspection: 21-01-21		District: East Champaran
Division: Arrah		Length (km):
Name of the Road: Manik Pur Kedar Sah School to Mahaganai Mahala Tolu		
Scheme/Programme: MAINTENANCE		
Findings No.:		Road ID No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a time off: New Connectivity/Up gradation/ Maintenance		
a) Road Junction condition		SU
b) Condition of Surfacing		SU
c) Riding Quality		SU
d) Road Camber		SU
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f) Contraction Joints provided or not (CC Pavement)		Yes/No
g) Compaction of flank/slope & rainouts if any		Yes/No
a) Condition of head walls in Hume pipe culverts including its painting		S/SU/U
b) Condition of Abutment & Wing walls, slab in RCC culverts		S/SU/U
c) Condition of railings/slab/approach for Bridges		S/SU/U
a) Whether sign boards/informatory/cautionary Board/km & 200m stone/Pavement road markings are provided and maintained		Yes/No
a) Status of ATR's & any others		N/D

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

NAME: Harinder Singh

DESIGNATION: DE. R.W.D.

Arrah

466
21/01/21
(Signature)