

FIELD INSPECTION REPORT

Date of Inspection :	18.12.21	District:	Saranagar
Division :	Saranagar	Length (km):	
Name of the Road:	Lot 4 Bhalu Chaur to Singhiyahi Jute bus Patchbar H. Tala		
Scheme/Programme:	MAINTENANCE		
Package No.:	MMGSY (Sc)	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓/Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Construction History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SI)

Unsatisfactory (U)

18/12/21

(Signature)