FIELD INSPECTION REPORT

Date of Inspection:							
Date of Inspection: 21/01/2021			District: KishanganT				
Name of the Road: Tos soriva derekto do southad: tak							
CI In							
Scheme/Programme: MMGISY							
Package No.: Road Id No.:							
Status of the Project: Ongoing/Completed /Under Maintenance							
Work is a case of: New Connectivity/ Up gradation / Maintenance							
\$1. No	Parameters to be checked,				Remarks		
1.	Pavement				S/U		
a)	Road Junction Condition			S/U			
b)	Condition of Surfacing \(\tag{\chi}\)				<u>\$</u> /U		
c)	Riding Quality			S/U			
d)	Road Camber				S/U Yes/No		
e)	Whether free from defects such as visible cracks, exposed aggregates						
1	in case of CC Pavement.						
f)	Contraction Joints Provided or not (CC Pavement)				Yes/No		
g)	Compaction of flank / shop & raincuts if any Yes/No						
2.	Cross Drainage						
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U			
b)	Condition of Abutment & Wing walls, slab in RCG culverts			S/SRI/U			
(c)	Condition of railings/Slab/approach for Bridges S/SRI/U						
3.	Road Furniture						
(a)	Whether sign boards/informatory/cautionary Board/km & 200m				Yes/No		
	stones/Paveme	nt road markings	are provided and maintained				
4.	Compliance History						
a)	Status of ATR's	& any others					

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory(U)	w _

(Signature)

NAME: Ranjeet Kumar

AE