

mmcy(uc)

FIELD INSPECTION REPORT

Date of Inspection: 28/01/21	District: EAST CHAMARAVEL
Division: ARVYD	Length (km):
Name of the Road: MAHAWA	Tola To 6047
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No: 511083013005010
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Contract/Up gradation/ Maintenance	
2.2. ROAD CONDITION	
a) Road/Junction condition	BU
b) Condition of Surfing	BU
c) Riding Quality	BU
d) Road Camber	BU
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Construction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & rainouts if any	Yes/No
2.3. BRIDGE CONDITION	
a) Condition of head walls in Hume pipe culverts including its painting	S/SU/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SU/U
c) Condition of railings/slab/approach for Bridges	S/SU/U
a) Whether sign boards/informatory/mandatory Board/km & 200m stream/Pavement road markings are provided and maintained	Yes/No
a) Status of ATR's & any others	

Overall Rating

Satisfactory (B)	
Satisfactory but requires improvement (SB)	
Unsatisfactory (U)	

NAME: Narasimhan Siva

DESIGNATION: AE

RVD Aravij

4/11/21
22/01/21
(Signature)

Scanned with CamScanner