

11/04/2020

ROAD INSPECTION REPORT

Date of Inspection: 26/01/20	Location: East Chawpaw
Division: JICA	Length (km):
Name of the Road: Baka Tals to 3048	
Section/Programme: MAINTENANCE	
Project No.:	Road ID No: 512-07815000-01
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is done at:	Other Condition/By previous maintenance
Road Condition	
Remarks	
a) Road Junction condition	BU
b) Condition of Surfacing	BU
c) Riding Quality	BU
d) Road Curb	BU
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Traffic
f) Construction Joints provided or not (CC Pavement)	Traffic
g) Composition of fill/drainage & culverts if any	Traffic
Drainage	
a) Condition of road profile in those place culverts including its piling	SSSBU
b) Condition of Alignment & Wing walls, Sub WCC culverts	SSSBU
c) Condition of drainage/retaining wall for bridge	SSSBU
Safety	
a) Whether sign board/informatory/warning location & size conform to road markings are provided and maintained	Traffic
Other	
a) State of ATR's & any other	

Overall Rating

Satisfactory (S)	
Satisfactory but require improvement (SS)	
Dissatisfactory (D)	

NAME: Hira Datta

DESIGNATION: AE

Signature: Hira