

MNGSY (U.O.)

# FIELD INSPECTION REPORT

Date of Inspection: 22/11/21	Location: East Chawpagan
Division: Pw. 233	Length (km):
Name of the Road: Maketo Tala To Lo 48	
Scheme/Programme: MAINTENANCE	
Project No.:	Road ID No: 319-030130054-00
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a new rd: New Construction/Up gradation/ Maintenance	
<b>General</b>	
a) Road Junction condition	SU
b) Condition of Surfacing	SU
c) Riding Quality	SU
d) Road Camber	SU
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f) Construction Joints provided or not (CC Pavement)	Yes/No
g) Comparison of flank/slope & drainage if any	Yes/No
<b>Drainage</b>	
a) Condition of head walls in Flow pipe culverts including its painting	S/SU/U
b) Condition of Abutment & Wing walls, slab at RCC culverts	S/SU/U
c) Condition of railings/slab/approach for Bridges	S/SU/U
<b>Signage</b>	
a) Whether sign boards/infrastructure/auxiliary Board/lan & 200m status/Pavement road markings are provided and maintained	Yes/No
<b>Other</b>	
a) Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SIS)	
Unsatisfactory (U)	

NAME: Harinder Jol

DESIGNATION: AE

RWD. Asray

Scanned with CamScanner