

FIELD INSPECTION REPORT

Date of Inspection: 25-12-2020	District: Buxar
Division: Buxar	Length (km): 3.25 Km
Name of the Road: Rajpur - Khatola mucharjoli to chaubaypur via Gogianichok	
Scheme/Programme: MAINTENANCE	MMGSY (WB)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: ✓ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & names Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

25-12-2020
NAME:

[Signature]
25-12-2020
(Signature)
J. K.
R. W. D. Rajpur