

Charkha

FIELD INSPECTION REPORT

Date of Inspection:	17/01/2021	Inspector: C. T. AYYA
Division:	Chennai	Length (km): 115 km
Name of the Road:	Thirumangalam Road	From: To: Padiyur Taluk, Tamil Nadu, India
Scheme/Programme:	MAINTENANCE	Year: 2021 (BC)
Package No.:	Road 1A 4A	
Status of the Project:	Ongoing/Uncompleted/Under Maintenance	
Work is a part of:	New Connectivity & Improvement Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raintcuts if any	Yes/No
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating :		
Satisfactory (S)		100% Yet Start
Satisfactory but requires Improvement (SRI)		SRI
Unsatisfactory (U)		

*D. T. Ayya
17/01/2021
092
Charkha*

(Signature)

NAME:

DESIGNATION: