

MNGSY(LWA)

FIELD INSPECTION REPORT

Date of Inspection	26/01/21	District	East Champaran																																													
Division	Arraj	Length (km)																																														
Name of the Road	Chandrabhai Cold Storage To Sachha																																															
Scheme/Programme	MAINTENANCE																																															
Package No.																																																
Status of the Project	Road Id No. 317087 E + 12																																															
Work is a part of	New Connectivity/Up gradation/ Maintenance																																															
<table border="1"> <thead> <tr> <th>Sl. No.</th> <th>Particulars</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>a)</td> <td>Road Junction condition</td> <td>SU</td> </tr> <tr> <td>b)</td> <td>Condition of Surfacing</td> <td>SU</td> </tr> <tr> <td>c)</td> <td>Riding Quality</td> <td>SU</td> </tr> <tr> <td>d)</td> <td>Road Camber</td> <td>SU</td> </tr> <tr> <td>e)</td> <td>Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement</td> <td>SU</td> </tr> <tr> <td>f)</td> <td>Contraction Joints provided or not (CC Pavement)</td> <td>Yes/No</td> </tr> <tr> <td>g)</td> <td>Compaction of Bank/slope & reinstatement if any</td> <td>Yes/No</td> </tr> <tr> <td colspan="3"> <table border="1"> <thead> <tr> <th>Sl. No.</th> <th>Particulars</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>a)</td> <td>Condition of head walls in Hume pipe culverts including its painting</td> <td>S/SR/U</td> </tr> <tr> <td>b)</td> <td>Condition of Abutment & Wing walls, Slab in RCC culverts</td> <td>S/SR/U</td> </tr> <tr> <td>c)</td> <td>Condition of millings/slab/approach for Bridges</td> <td>S/SR/U</td> </tr> <tr> <td>d)</td> <td>Whether sign boards/informatory/Warning Board/Km & 200m stone Pavement road markings are provided and maintained</td> <td>Yes/No</td> </tr> </tbody> </table> </td> </tr> <tr> <td>e)</td> <td>State of ATR's & any others</td> <td></td> </tr> </tbody> </table>				Sl. No.	Particulars	Remarks	a)	Road Junction condition	SU	b)	Condition of Surfacing	SU	c)	Riding Quality	SU	d)	Road Camber	SU	e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	SU	f)	Contraction Joints provided or not (CC Pavement)	Yes/No	g)	Compaction of Bank/slope & reinstatement if any	Yes/No	<table border="1"> <thead> <tr> <th>Sl. No.</th> <th>Particulars</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>a)</td> <td>Condition of head walls in Hume pipe culverts including its painting</td> <td>S/SR/U</td> </tr> <tr> <td>b)</td> <td>Condition of Abutment & Wing walls, Slab in RCC culverts</td> <td>S/SR/U</td> </tr> <tr> <td>c)</td> <td>Condition of millings/slab/approach for Bridges</td> <td>S/SR/U</td> </tr> <tr> <td>d)</td> <td>Whether sign boards/informatory/Warning Board/Km & 200m stone Pavement road markings are provided and maintained</td> <td>Yes/No</td> </tr> </tbody> </table>			Sl. No.	Particulars	Remarks	a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	c)	Condition of millings/slab/approach for Bridges	S/SR/U	d)	Whether sign boards/informatory/Warning Board/Km & 200m stone Pavement road markings are provided and maintained	Yes/No	e)	State of ATR's & any others	
Sl. No.	Particulars	Remarks																																														
a)	Road Junction condition	SU																																														
b)	Condition of Surfacing	SU																																														
c)	Riding Quality	SU																																														
d)	Road Camber	SU																																														
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	SU																																														
f)	Contraction Joints provided or not (CC Pavement)	Yes/No																																														
g)	Compaction of Bank/slope & reinstatement if any	Yes/No																																														
<table border="1"> <thead> <tr> <th>Sl. No.</th> <th>Particulars</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>a)</td> <td>Condition of head walls in Hume pipe culverts including its painting</td> <td>S/SR/U</td> </tr> <tr> <td>b)</td> <td>Condition of Abutment & Wing walls, Slab in RCC culverts</td> <td>S/SR/U</td> </tr> <tr> <td>c)</td> <td>Condition of millings/slab/approach for Bridges</td> <td>S/SR/U</td> </tr> <tr> <td>d)</td> <td>Whether sign boards/informatory/Warning Board/Km & 200m stone Pavement road markings are provided and maintained</td> <td>Yes/No</td> </tr> </tbody> </table>			Sl. No.	Particulars	Remarks	a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	c)	Condition of millings/slab/approach for Bridges	S/SR/U	d)	Whether sign boards/informatory/Warning Board/Km & 200m stone Pavement road markings are provided and maintained	Yes/No																															
Sl. No.	Particulars	Remarks																																														
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U																																														
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U																																														
c)	Condition of millings/slab/approach for Bridges	S/SR/U																																														
d)	Whether sign boards/informatory/Warning Board/Km & 200m stone Pavement road markings are provided and maintained	Yes/No																																														
e)	State of ATR's & any others																																															

Overall Rating

Satisfactory (S)	
Satisfactory but requires improvement (SI)	
Unsatisfactory (U)	

NAME: Harshvardh Enk
 DESIGNATION: AE
 QUD. Arraj

26/01/21
 (Signature)