## FIELD INSPECTION REPORT

Data act		15 01.2021	District: SF	eikhpura	
Date of Inspection: 0/7.0/.202/ District: Sheikhpuna  Division: Sheikhpuna Length (km): 0.600					
Name of the Road: Zila Simana Sheikhpura to Sumka Yadan Tola					
Scheme/Programme: MAINTENANCE Ongoing Total					
Road d No.					
Status of the Project: Ongoing Compressed Charles and Charles					
Work is	a case of:	New Connectivity/U	ew Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked		Remarks
THE STATE OF	Paventent -	Star Path Bull Ten Laborat	色子生的情况		
A STATE OF THE STA		. 1		-	√8/U
b)	Condition of S	urtacing			Sin
c)	Riding Quality				√S/U
_ d)	Road Camber				√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				-Ves/No
a)	Condition of head walls in Hume pipe culverts including its painting				8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				/S/SRI/U
c)	Condition of railings/slab/approach for Bridges				√S/SRI/U
3	Road Furnitu	Commission of the Commission o			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stress/Payemen' and maintained				Yes/No
14.4E	Compliance	listory			
a)	Status of ATR's & any others				
Overall	Kating :	Satisfactory (S)			
		Satisfactory bu	t requires Impro	vement (SRI)	
		Unsatisfactory	(U)		i, r.

(Signature)

NAME: PANKAT KUMAR

DESIGNATION: JE, ARIYARY