PDF Compressor Free Version

Inspection Report for Flood Damage Work

Dale:

- 1. Name of PIUs RWD works Division, Grobaldary -2
- 2. Name of Block/Road-Sidhwalia / Thajhwa to Saleh pur

A. For Road

- 1. Damage Location/Chainage
- : 2800,M | 6900M | 7300M : 22.0 M | 22.0 M 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works: Brick bats, Sand billed Cement bag
 - Equipments/Tools being used in Restoration works: JCB, Tractor with Frully ii.
 - Procedure taken up in Restoration works:
 - iv. Restored Length

: 54.0M

B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length

3. Nature of Damage

- 4. Details of Restoration Works
 - Material being used in Restoration works: i.
 - Equipments/Tools being used in Restoration works: ii.
 - Procedure taken up in Restoration works: iii.
 - Restored Length iv.

(Name of Inspector)



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

FLOOD DAMAGED REPAIR (F.D.R)

STATE :- BIHAR DISTRICT :- GOPALGANJ BLOCK :- SIDHWALIA

Jhajhwa to Salehpur

ESTIMATED COST RS 477400.00

SUBMITTED BY: EXECUTIVE ENGINEER RWD (W) DIVISON-GOPALGANJ-2

Report.

Name of work

:- Jhajhwa to Salæhpur

Estimated Cost

:- Rs 4,77,400.00

Total length of road :- 8.565

Description :- The present estimate has been framed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter no – 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transportation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. There has also been a provision of filling sands in the empty cement packets, and afterward putting those sand bags along the borders of road. This provision has a purpose to put a check on the erosion of embankment along the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

18-09-20 J.E.

A.E.

E.E.

PDF Compressor Free Version

Testimate For Motorable Work in road from Jhajhwa to Salehpur damaged due Heavy rain / Flood for Year . 2020-2021

Sr.	Items	no.	L (M.)	W 11.	T = ===		_	,	
	Providing brick bats billed in ditches	110,	L (M1.)	W M.)	D (M.)	Qty.	unit	rate	Amount
	including all cost of Labour & Material with all complete job.								3
	CH- 5800 M to 6000 M	1	24.00	1.10	2.00	52.80	M ³		_ `
_	CH - 6900 M to 7000 M	1	5.00	1.00	1.30	6.50	M ³		— ; —
		1	3.00	1.00	1.30	3.90	M ³	-	
	CH - 7300 M to 7400 M	1	9.00	1.00	3.00	27.00	M ³		
		1	13.00	1.00	3.00	39.00	M ³	2412-1	311645=
	Providing Empty Cement Bag billed with					129.20	M^3	2427.65	3.13,652,38
	local Sand Stiching placing on proper place with all cost of lab & Material & all Complete Job								
	CH -5800 M to CH - 5900 M	1	24.00	1.40	2.00	67.20	M ³		
	CH -5900 M to CH - 7000 M	1	5.00	1.40	1.30	9.10	M ³		
		1	3.00	1.40	1.30	5.46	M ³		
	CH - 7300 M to CH - 7400 M	1	9.00	1.40	3.00	37.80	M ³		
		1	13.00	1.40	3.00	54.60	M ³		
_						174.16	M ³	24.74	152418~
_	Nos . Of Bags 174.16 x 35.31 / 1.20					5125.00		31.04	159,080.00
								464068	24727\$2.38
	Add 1% contigency							46412	477.32
_								Total	477459.70
_								Say	4,77,400.00

Technically Approved for Ro 4.687 Lac (Rupres Four Lac 8144 Thousehold & Seven Hunand only

Superintending Enginee