PDF Compressor Free Version Report for Flood Damage Work

-		
- 1	late	٠
4	ale,	

1. Name of PIUs	RWD Works	Division, Gropoul	Glani-
-----------------	-----------	-------------------	--------

2. Name of Block/Road - Sidhwalia / Vishunpur - Jallalpur PMusy road to Bhuminar tola Sidhualia. Balding road

A. For Road

1. Damage Location/Chainage

2. Damage Length

: Board markant & bourtingth morphat: 33.0W | 11.0W | 12W 3. Nature of Damage

4. Details of Restoration Works

Material being used in Restoration works: Brick bads, Sound billed c. bog.

ii. Equipments/Tools being used in Restoration works: JC & Fractord Trolly

iii. Procedure taken up in Restoration works:

iv. Restored Length

MG.811

B. For Bridge

Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

Material being used in Restoration works:

Equipments/Tools being used in Restoration works: ii.

Procedure taken up in Restoration works: iii.

Restored Length iv.

Name of Inspect



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

FLOOD DAMAGED REPAIR (F.D.R)

STATE :- BIHAR DISTRICT :- GOPALGANJ BLOCK :- SIDHWALIA

Vishunpur jallalpur PMGSY road to Bhumihar tola Sidhwalia - Baldiha

ESTIMATED COST RS 829500.00

SUBMITTED BY: EXECUTIVE ENGINEER RWD (W) DIVISON-GOPALGANJ-2

Report.

Name of work

:- Vishunpur jallalpur PMGSY road to Bhumihar tola Sidhwalia - Baldiha

Estimated Cost

:- Rs 829500.00

Total length of road :- 3.40 KM

Description :- The present estimate has been framed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter no — 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transportation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. There has also been a provision of filling sands in the empty cement packets , and afterward putting those sand bags along the borders of road . This provision has a purpose to put a check on the erosion of embankment along the road .

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

18-09 20 J.E.

A.E.

E.E 9/20

PDF Compressor Free Version Detailed Estimate For Motorable Work in road from Vishunpur jallalpur PMGSY road to Bhumihar tola Sidhwalia - Baldiha PWD road damaged due to Heavy rain / Flood for

v	0	25	20	20	\sim	2	2	24	
1	C (31	2	JΖ	U-	~	U	4	

Sr.	. Items	no.	L (M.)	W M.)	D (M.)	Qty.	unit	t rate	Amount
1	Providing brick bats billed in ditches including all cost of Labour & Material with all complete job.							Line	Amount
	CH- 100 M	1	14.00	3.60	1.50	75.60	M ³	-	
_		1	19.00	4.50	1.50	128.25	M ³	-	
	CH- 160 M	1	11.00	1.40	1.00	15.40	M ³	-	
_/	CH- 500 M	1	25.00	1.00	0.15	3.75	M ³		
	Near Culvert	2	2.00	2.00	2.30	18.40	M ³		
_		1	1.00	2.00	2.30	4.60	M^3		
	1	1	15.00	1.5	1.00	22.50	M^3		
		1	15.00	2.00	1.00	30.00	M^3		
		1	15.00	1.75 M (AV)	1.20	31.50	3 .3	2412.11	7-45996=1
						330.00	-	2427.65	
	Providing empty cement bags filled with load								Total Maria Special Sp
		2	3.00	1.20	2.30	16.56	M ³		
		1	2.00	1.20	2.30	5.52	M ³	2412.11	532592
/	<u> </u>					22.08		2427.65	53602.51
	No. of Bags 22.08x35.3/1.20					650.00		31,04	20176.00 933
		\sqcup						21.11	821300.30 968.
	Add 1% contigency	\sqcup						/ - V	8213.01 8686
	1						+	Total	8 29513.5 1
'							1	Say	829500.00

Zuy Ry 8.773 L

Technically Approved for R 8-773 Lac (Respect Gight Lee Ser Seven Thousand & Three Hundred) why

15/01/2) Superintending finginge P.M.D. Wlerk, Circle C.