

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- P / PWD 77 Sadak Primary health Centre to big Bhunsiya

(A) For Road:

to PWD to Kharsa and Minapur PWD road to Tulsahi

1. Damage Location/Chainage :- 0.900 km, 0.900 km

2. Damage Length :- 0.123 km

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- brick bats

(ii) Equipment's/Tools being used in Restoration works:- tractor

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- 0.123 km

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

EE

RWD Muzabbarpur East-1

### GENERAL ABSTRACT

Name of Road PWD 77 Sadak Primary Health center Via Bhureniya to PWD to Kharara and Minapur PWD Road to Tulsahi  
District Muzaffarpur  
Block Minapur  
Division Muzaffarpur East-2  
Length of Road (in Km) 4.107 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	11.023
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	11.023
TOTAL COST OF PROJECT IN LACS =		11.023

Say 11.02 lac

*[Signature]*  
11/01/21

JE  
RWD

*[Signature]*  
11/01/17

AE  
RWD

*[Signature]*  
22/17

EE  
RWD

Technically approved for Rs 11.02 lac  
(Rupees Eleven lac two thousand only)

*[Signature]*  
SE 13.11.17

RWD work circle  
muzaffarpur