

GENERAL ABSTRACT

Name of Road	Rajnath Singh House to Milki Pokhar
--------------	-------------------------------------

District Muzaffarpur

Block	Bochaha
-------	---------

Division Muzaffarpur East-2

Length of Road (in Km)

1.007 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.248
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	9.248
TOTAL COST OF PROJECT IN LACS =		9.248

Say 9.25 lac

31/12/2020

JE
RWD

~~Agg~~ 31/12/20

AE
RWD

On

EE
RWD

Technically Approved for B3 9.25 L4L

(Pepees nine Lac twenty five thousand only.)

16-1-7

SE
RWD work circle
myziflorphos

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- 6492 vibhaskar

2 Name of Block/Road :- Rajmath singh house to milki pokhar

(A) For Road: ✓

1. Damage Location/Chainage :- 0.150km, 0.20km, 0.350km, 0.450km, 0.60km, 0.950km
2. Damage Length :- 0.05005km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- bricks bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.05005km

(Length = 1.007 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD WORKS DIVISION
Muzaffargarh East-I