

FIELD INSPECTION REPORT

Date of Inspection: 19/11/20		District: Shashipuri
Division: RWD Shashipuri		Length (km): 0.900 km
Name of the Road: Chawara to Han Path to Chathiyam Beldara 2019.		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
	condition of surface	U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Gross Drainage		
Condition of water ways in terms of silt, debris, obstructions, etc.		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	Y
Unsatisfactory (U)	-U-

19/11/20
(Signature)

NAME: ANN M

DESIGNATION: PE