FIELD INSPECTION REPORT

BLOCK JALALPUR

-	-			
The state of the s	the same of the sa	20,01,201	District: Sax	in (chapter)
Division: chapra-2-				oo km
	f the Road: No			Surgerder Sing
	/Programme:	MAINTENANCE		chumitant
Package No.:			Road Id No.:	Bhumi M2-T
The state of the s			//Under Maintenance	
WOLK IS	n case or:	COLUMN THE PROPERTY OF THE PARTY OF THE PART	/Up gradation/ Maintenance	SPECIAL HEAVING DATE OF
SING		The second of th	to be checked	1 Kalimika
10	Payement 1	Alleria de Calda	Asia di Paranta di Angaran Ang	
a)	Road Junction	√\$/U		
b)	Condition of S	\s\ru		
c)	Riding Quality	S/U		
d)	Road Camber	√S/U		
c)	Whether free aggregates in c	rposed Yes/No		
Ŋ	Contraction Joints provided or not (CC Pavement)			√Yes/No
g)	Compaction of	√Yes/No		
2	Gross Drainag			
a) .	Condition of he	iinting S/SRI/U		
b)	Condition of A	\$/SRI/U		
c)	Condition of railings/slab/approach for Bridges			· S/SRI/U
312	Roid Furnitin	0		
a)		T = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 =	/cautionary Board/km & provided and maintained	200m Yes/No
Maria	Compliance Hi	story		
a)	Status of ATR's	& any others	A Committee of the Comm	HO ATR

Overall Rating

Satisfactory (S)	Annual .
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	American a

(Signature)

NAME: Mritungon Kerman

DESIGNATION: JE