

FIELD INSPECTION REPORT

Date of Inspection : 22/12/2020	District: Samastipur
Division : Samastipur	Length (km): 1.415 KM
Name of the Road: To Gimesnagar Kishanpur Path to Guleb Chowk to Mahadali	
Scheme/Programme:	MAINTENANCE
Package No.: MMGSV (SC)	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sr. No.	Parameters to be checked	Remarks
Pavement		
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
Cross-Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Sahjandra Narayana

(Signature)

22/12/2020
A