


FIELD INSPECTION REPORT

Date of Inspection :	23/12/2020	District:	Bhagpur
Division :	D120	Length (km):	
Name of the Road:	T62 To Pitambarpur		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-07R-307	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	~ S/U	
d)	Road Camber	~ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U


(Signature)

NAME: Jomesh Chaudhary
J.E

- (i) Rectification done or Not? - *Not*
- (ii) Work Started or Not? - *Not*
- (iii) Notice issue by PIU or Not? - *Yes*
- (iv) Rectification Started or Not? - *Not*
- (v) Comment if Any? - *-*
- (vi) Grade - *U*
- (vii) Upload image (max 5 image) - *Yes*
- (viii) Upload inspection Report PDF format - *Yes*