

FIELD INSPECTION REPORT

Date of Inspection:	21.1.2021	District:	Madhyanagar
Division:	R.W.D. Bhatkal	Length (km):	1.0 km
Name of the Road:	S. G. de Rai Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:	318088/2003	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓(S)
b)	Condition of Surfacing	✓(S)
c)	Riding Quality	✓(S)
d)	Road Camber	✓(S)
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓(S)
f)	Contraction Joints provided or not (CC Pavement)	✓(S)
g)	Compaction of flank/slope & raincuts if any	✓(S)
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓(S)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓(S)
c)	Condition of railings/slab/approach for Bridges	✓(S)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓(S)
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

(Signature)

NAME:

DESIGNATION:

[Signature]
21.1.2021