FIELD INSPECTION REPORT

Date of Inspection: 22/01/21			District: Lakhi sera	
Division: Lakhisorai Length (km): 1.610				
	the Road:		nza Nafor to Bajity	
	Programme:	MAINTENANCE		
Package	No.: States	cheme (NABARD	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	a case of:	New Connectivity/	Up gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remark
1.	Payement		involverality in the account of	
a)	Road Junction	870		
b)	Condition of Surfacing			~87U
c)	Riding Quality			1870
d)	Road Camber			√8/U
e)	Whether free aggregates in c	Xes/No		
f)	Contraction Joints provided or not (CC Pavement)			¥es/No
g)	Compaction of	Yes/No		
2.	Cross Drainag	(o		

Condition of head walls in Hume pipe culverts including its painting

Condition of Abutment & Wing walls, Slab in RCC culverts N.A.

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Condition of railings/slab/approach for Bridges

Overall Rating

a)

b)

c)

3.

a)

a)

Road Furniture

Compliance History

Status of ATR's & any others

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI
Unsatisfactory (U)	OKI

201010001 AE

8/SRI/U

S/SRI/U

S/SRI/U

Yes/No

NA

N.A

(Signature)

INAIVIE		