

FIELD INSPECTION REPORT

Date of Inspection : 16/01/2021	District: Begusarai
Division : Tega/A	Length (km): 0.600 KM
Name of the Road: TOI NH 28 p/m/ ex. Path to Koul 2 Charaka Tola	
Scheme/Programme: MAINTENANCE	
Package No.: C9TGNY	Road Id No.: 320070R029
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & minimum if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/RI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/RI/U
c)	Condition of railings/slab/approach for Bridges	✓S/RI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	—
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Urnash Kumar Mehta
 DESIGNATION: Junior Engineer

16.1.21

Signature
 16/01/2021