

FIELD INSPECTION REPORT

Date of Inspection : 10-01-2021		District: Sarmaahpur	
Division : DA DVI		Length (km): 1.00 Km	
Name of the Road: Enayatpur Ghushan Ray ka ghata se (to) ita chumwa rak			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	8/U	u
b)	Condition of Surfacing	8/U	u
c)	Riding Quality	8/U	u
d)	Road Camber	8/U	u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	crack
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NOT
g)	Compaction of flank/slope & raincuts if any	Yes/No	u
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRT/U	u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRT/U	u
c)	Condition of railings/slab/approach for Bridges	S/SRT/U	u
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	u
4. Compliance History			
a)	Status of ATR's & any others		u

Overall Rating :

Satisfactory (S)	u
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Aras kumar singh
DESIGNATION: J.E

10/01/2021
(Signature)