TOTION REPORT

	FIELD INSPECTION REPORT	W.C.	1
	of Inspection: 13/61/2021 District: 30maship ion: PATOYI Length (km): of the Road: Mohampur parkhand Antergal Moham no Programme: MAINTENANCE Road Id No.	L. Whazi	pa
Date	of Inspection: Length (km):	pur to pri	-
Name	of the Road: Mohan Pul Dat Knano Hill	10.0	-
	ne/Programme: MAINTENANCE Road Id No.:	naoiris	
Was a Bridge	ge No.: of the Project: Ongoing/Completed/Under Maintenance of the Project: Ongoing/Completed/Under Maintenance		
Status .	New Connecti	Remark	4
Vork is	Parameters to be checked	Kemark	S
1.	Pavement		Č.
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		-
d)	Road Camber		-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage	A CONTRACTOR OF THE PARTY OF TH	
a)	Condition of head walls in Hume pipe culverts including its painting	ng S/SRI/U	1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	1
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	+
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained	m Yes/No	
4.	Compliance History		5
a)	Status of ATR's & any others	NO ATR	1

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Aday Kuman singh stym DESIGNATION: -> E

(Signature)