FIELD INSPECTION REPORT

Date of Inspection : Division :	Llad chauck	District: Length (km): +0 PMGSY	
Scheme/Programme: MAINTENANCE Package No.: Status of the Project: Ongoing/Completed/Under Maintenance Ongoing/Completed/Under Maintenance			
Vork is a case of:	Parameters to l		Remark
1. Pavement			and the second section
a) Road Junction	Road Junction condition		
b) Condition of S	Condition of Surfacing		
c) Riding Quality	Riding Quality		
d) Road Camber	Road Camber		
6)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f) Contraction Jo	Contraction Joints provided or not (CC Pavement)		
g) Compaction of	Compaction of flank/slope & raincuts if any		
2. Cross Draina	ge		
a) Condition of h	Condition of head walls in Hume pipe culverts including its painting		
b) Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts		
c) Condition of ra	Condition of railings/slab/approach for Bridges		
3. Road Furnitu	Condition of railings/slab/approach for Bridges S/SRI/U Road Furniture		
a) Whether sign stones/Pavement	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4. Compliance H	Compliance History		
a) Status of ATR'	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: AJOY KYMER SIMP 19/01/2021

DESIGNATION: ¬. €

(Signature)