

FIELD INSPECTION REPORT

of Ammabes / B. N. C.

Date: 21/01/2021
 W. 30966shpur

District: Bhojpur

Length (km): 127.5 km

Name of the Road: Bihiga Tiyar Road to Dalpatpur

Scheme/Programme: MAINTENANCE

Package No.: Road Id No.: 10401701903

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	NO
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

21/01/2021
 08

21/01/2021
 (Signature) A E