

FIELD INSPECTION REPORT

old mm 6.84/13110

Date of Inspection : 21/01/2021 District: Bhadrachalam
 Division : AW 2 Sargolshapur Length (km): 1.60 km
 Name of the Road: Bhriga Tron Road to Hridayapur
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 10401701904
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U - S
c)	Riding Quality	S/U - S
d)	Road Camber	S/U - S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U X
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

21/01/2021
SE

21/01/2021
(Signature) AW

NAME: