## FIELD INSPECTION REPORT

			District: Shellah	toura
Date of inspection.				m
DIVISION:				
Name of the Road.				
Scheme/Programme: MAINTENANCE  Package No.: Road Id No.:				
1 acrage 110				
Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Maintenance			n gradation/ Maintenance	
THE RESERVE OF THE PARTY OF THE				Remarks
SI. No.		Parameters 10	Descrice Constitution of the Constitution of t	
10.5	Pavement			
a)	Road Junction condition			∕8/U
b)	Condition of Surfacing			<b>√8/U</b>
c)	Riding Quality			√8/U
d)	Road Camber			√8//U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/Nø
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts			-8/SRI/U
c)	Condition of railings/slab/approach for Bridges			s/sri/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4	Compliance History			
a)	Status of ATR's & any others			
Overall	Rating :	Satisfactory (S)		

Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: PANKAJ KUMAR

DESIGNATION: JE, Glat kusumbha