

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Bibhakar

2 Name of Block/Road :- Bhojla to Karna iorax

(A) For Road: ✓

1. Damage Location/Chainage :- 0.325km, 0.475km, 0.595km, 0.715km, 0.925km, 1.21km, 1.50km, 1.65km
2. Damage Length :- 0.654km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.654km

(Length 1.75km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD Work Division
myzikkapur East-1

GENERAL ABSTRACT

Name of Road Bhorha to Kaynalnnar

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km)

1.750 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	21.602
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	21.602
TOTAL COST OF PROJECT IN LACS =		21.602

say 21.60 Lac

(Signature)
31/12/2020
JE
RWD

(Signature)
31/12/20
AE
RWD

(Signature)
21/12
EE
RWD

Technically Approved for Rs 21.60 Lac
(Rupees twenty one Lac sixty thousand only).

(Signature)
16.1.21
SE
RWD work circle
muzaffarpur