

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vi'bhakar

2 Name of Block/Road :- Pshulpur to Kanya Enar same wali' sharak tak

(A) For Road: ✓

1. Damage Location/Chainage :- 0.280km, 0.440km, 0.520km, 0.680km, 0.900km, 1.20km, 1.450km.
2. Damage Length :- 0.662km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.662km

(Length = 1.50km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD work division
myzaffar pur East I

GENERAL ABSTRACT

Name of Road Rshulpur to Kanya Enar Jane Wali Sharak Tak

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 1.500 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	17.861
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.359
	GRAND SUB TOTAL	18.220
TOTAL COST OF PROJECT IN LACS =		18.220

say 18.22 Lac


31/12/20
JE
RWD


31/12/20
AE
RWD


31/12/20
EE
RWD

Technically Approved for Rs 18.22 Lac
(Rupees eighteen Lac twenty two thousand only.)


16.1.21
SE
RWD work circle
muzaffarpur