

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Sarfoddinpur p.w.D Rd to Gurm

(A) For Road: ✓

1. Damage Location/Chainage :- 0.900km, 1.10km, 1.30km, 1.45km, 1.60km, 1.76km
2. Damage Length :- 0.230km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.230km

(Length = 1.80km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD WORK Division
muzaffarpur East 1

GENERAL ABSTRACT

Name of Road Sarfaddimpur PWD Rd to Gurmi(00-01)

District Muzaffarpur

Block Bochaha


Division Muzaffarpur East-2

Length of Road (in Km) 1.850 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.798
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.798
TOTAL COST OF PROJECT IN LACS =		3.798


Say 3.80 Lac


JE
RWD


AE
RWD


EE
RWD

Technically Approved for Rs 3.80 Lac
(Rupees three Lac eighty thousand only.)


SE
RWD work circle
muzaffarpur