

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- maweti hospital to pyneewari Borch.

(A) For Road: ✓

1. Damage Location/Chainage :- 1.50km, 1.80km, 1.95km, 2.20km, 2.310km, 2.42km
2. Damage Length :- 165.80m (0.1651km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.1651km

(Length = 3.050km)

(B) For Bridge: X

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RWD work Division
myzafferpur Ecet-1

GENERAL ABSTRACT

Name of Road Maweshi hospital to Purenwara Bandh

District Muzaffarpur

Block Bochara

Division Muzaffarpur East-2


Length of Road (in Km) 3.050 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.991
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	6.991
TOTAL COST OF PROJECT IN LACS =		6.991


SAY 6.99 LAC


JE


RWD


AE

RWD


RWD

Technically Approved for Rs 6.99 LAC
(Rupees six lac ninety nine thousand only).


SE
Road works circle
muzaffarpur