

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of Restoration of road from Ramjanki Sitakund to Bedlihan Machkuban Mallah Tola					
Head - E.D.R.					
Agency - Departmental					
E. A. RWD (W) Div. Chakia					
Date of Measurement -					
(1) Prov ⁿ laying at site B/Bat ^y on ditches - all p ^o Job					
1 X 12 X	5.50	8.00	1.85		149.85 M ³
1 X 7.0 X	5.50	8.00	1.50		70.88 M ³
1 X 10.0 X	5.50	8.00	1.29		87.08 M ³
					307.81 M ³

$$e h - 2147 = 40/M^3 \quad h - 6, 60.991 = \infty$$

(2) Provⁿ - sand filling in foundⁿ trench

$$1 \times 12.00 \times 6.75 \times 0.100 = 8.10 M^3$$

$$1 \times 7.0 \times 6.75 \times 0.100 = 4.73 M^3$$

$$1 \times 10.0 \times 6.75 \times 0.100 = 6.75 M^3$$

$$19.58 M^3$$

$$e h - 471 = 55/M^3 \quad h - 9233 = \infty$$

(3) Provⁿ and laying Rec

Pipe NP3 1000mm ϕ

$$1 \times 7.50 = 7.50 M$$

$$e h - 3594.14/M^3 \quad 26956 = \infty$$

(4) Provⁿ and laying Rec

Pipe NP3 1000mm

dia

Continuation

$$697180 = \infty$$

[illegible]

Continuation