

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Katoa / Gram Parsaul Rimbabu Parari House to Jugal Das House RBO Road Tak.


(A) For Road:

1. Damage Location/Chainage :- 0.100 to 0.540 km, 0.750 to 1.065 km
2. Damage Length :- 0.755 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Basic batis
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.755 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

BE

RWD muraadpur cult - 1

GENERAL ABSTRACT

Name of Road Gram Parsaul Rambabu Paravi House to Yougal Das House REO Road Tak

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 1.380 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.550
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	6.550
TOTAL COST OF PROJECT IN LACS =		6.550

say 6.55 lac

11/11/2021

JE
RWD

11.1.2021

AE
RWD

9/11/21
EE
RWD

Technically approved for Rs 6.55 lac
(Rupees six lac fifty five thousand only)

13.1.21
SE

RWD work circle
muzaffarpur