

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Katoa/sing wari gram RCO snak to laighe talai at kam suhat
Rw House via Shiv Shankar Paswan House

(A) For Road:

1. Damage Location/Chainage :- 0.030 Km, 0.800 km, 0.880 km
2. Damage Length :- 0.555 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Bricks
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.555 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD Muzattapur East-1

GENERAL ABSTRACT

Name of Road Singwari Gram REO Sarak to Rajghat Tol at Ram Sughat Rai House via Shiv Shankar Paswan House
District Muzaffarpur
Block Katra
Division Muzaffarpur East-2
Length of Road (in Km) 1.161 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.656
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	8.656
TOTAL COST OF PROJECT IN LACS =		8.656

say 8.656 lac

[Signature]
JE
RWD

[Signature]
AE
RWD

[Signature]
EE
RWD

Technically approved for Rs 8.656 lac
(Rupees Eight lac sixty five thousand six hundred only)

[Signature]
SE
13.1.21

RWD work circle
muzaffarpur