

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan-vibhakar

2 Name of Block/Road :- Rajiv chinni to Surya Dev smarak tak

(A) For Road: ✓

1. Damage Location/Chainage :- 0.245 km, 0.380 km, 0.580 km, 0.870 km, 0.965 km
2. Damage Length :- 0.602 km
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:- brick bed
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :- 0.602 km
- (Length 2 1.99 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AE/EE


11.1.21
Signature

(Name of Inspection)

EE

RWD Work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Rajiv Chinnai to Surya Dev Smarak Tak

District Muzaffarpur

Block Borchaha

Division Muzaffarpur East-2

Length of Road (in Km)

1.990 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	24.476
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	24.476
TOTAL COST OF PROJECT IN LACS =		24.476

Set 24.48 LAC

[Signature]
JE
RWD

[Signature]
AE
RWD

[Signature]
JE
RWD

Technically Approved for Rs 24.48 LAC
(Rupees twenty four LAC forty eight thousand only.)

[Signature]
S.E.
RWD work circle
muzaffarpur