

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Chapra Narma Rd to Hathauri PWD PadL

(A) For Road: ✓

1. Damage Location/Chainage :- 0.350km, 0.550km, 0.950km, 1.050km, 1.350km
2. Damage Length :- 0.225km 1.80km, 1.90km, 2.5km, 3.1km
3. Nature of Damage :- 3.6km, 4.9km
4. Details of Restoration Works :-
(i) Material being used in Restoration works:- brick bats.
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:
(iv) Restored Length :- 0.225km (Length = 6.8 km)

(B) For Bridge: X

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AB/EE


Signature

(Name of Inspection)

EC
RWD WORK DIVISION
Muzaffarpur Dist-1

GENERAL ABSTRACT

Name of Road Chapra Nurma Rd to Hathauri PWD Rd

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 6.800 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	15.294
2	Sand Filling	0.000
3	Sand bag	0.000
4	H P.	0.000
	GRAND SUB TOTAL	15.294
TOTAL COST OF PROJECT IN LACS =		15.294


Say 15.29 Lac


31/12/2020

JE
RWD


31/12/20

AE
RWD


31/12/20
EE
RWD

Technically approved for Rs 15.29 Lac
(Rupees fifteen lac twenty nine thousand only.)


16.1.21
SE
RWD work circle
muzaffarpur